

R. Rucinski  
9/8/2008

This document is a place holder. A variety of Job Hazard Analysis exist, stored in a separate location. (pathname: \\D0server6\dmacs\DZERO Docs\Safety Docs\JHA Job Hazard Analysis) These JHA's were written for activities by the PPD/MD/DZero Ops team at the DZERO assembly building. Below is a screenshot listing them as of September 8, 2008. Hard signed copies are kept in a binder in the cryogenic control room at DZero.

Sincerely, Russ Rucinski

Name	Size	Type	Date Modified
JHA_Turbomotor	44 KB	Microsoft Word Doc...	5/16/2008 2:38 PM
JHA closing detector	39 KB	Microsoft Word Doc...	4/16/2008 2:44 PM
JHA VME_remove	49 KB	Microsoft Word Doc...	4/10/2008 3:06 PM
Swapping exp. engines JHA	16 KB	Microsoft Word Doc...	3/21/2008 8:52 AM
JHA Opening AND Closing detector _Feb_08	57 KB	Microsoft Word Doc...	2/19/2008 12:46 PM
JHA D0 low beta quad curtain work	50 KB	Microsoft Word Doc...	8/8/2007 9:18 AM
JHA_Aftercooler_swap	58 KB	Microsoft Word Doc...	6/6/2007 4:47 PM
PPD guidelines on JHAs	306 KB	Adobe Acrobat Doc...	5/21/2007 1:02 PM
JHA_Relief_valve _change	48 KB	Microsoft Word Doc...	2/22/2007 11:36 AM
JHA_prv745	50 KB	Microsoft Word Doc...	12/11/2006 6:39 AM
DryerValveJHA	49 KB	Microsoft Word Doc...	11/14/2006 12:10 PM
DryerBedChangeJHA	48 KB	Microsoft Word Doc...	11/14/2006 11:56 AM
JHA Scaffold Use by experimenters PDT	35 KB	Microsoft Word Doc...	11/3/2006 2:18 PM
JHA opening detector	43 KB	Microsoft Word Doc...	9/25/2006 12:10 PM
JHA_ILC_air	43 KB	Microsoft Word Doc...	8/22/2006 2:55 PM
JHA EC beampipe weld	56 KB	Microsoft Word Doc...	4/19/2006 10:38 AM
EC Beampipe Welding	57 KB	Microsoft Word Doc...	4/17/2006 2:19 PM
Tedlar membrane removal JHA	67 KB	Microsoft Word Doc...	2/24/2006 2:10 PM
JHA motor swap	48 KB	Microsoft Word Doc...	1/17/2006 11:40 AM
JHA Scaffold Use by general	45 KB	Microsoft Word Doc...	12/7/2005 1:07 PM
JHA Ar Test Cell	32 KB	Microsoft Word Doc...	8/8/2005 10:44 AM
JHA Cold compressor connection	51 KB	Microsoft Word Doc...	5/18/2005 10:18 AM
Subcooler HX1408LN installation JHA	50 KB	Microsoft Word Doc...	5/20/2004 3:01 PM
443LNjha	50 KB	Microsoft Word Doc...	3/10/2004 9:41 AM
trailerjha	49 KB	Microsoft Word Doc...	3/3/2004 3:33 PM
DOEVXLN repair	16 KB	Microsoft Word Doc...	10/29/2003 5:04 PM
JHA forklift to storage	31 KB	Microsoft Word Doc...	9/5/2003 4:35 PM
JHA using air tool	43 KB	Microsoft Word Doc...	9/5/2003 4:28 PM
JHA tube trailer connecting	46 KB	Microsoft Word Doc...	9/5/2003 4:27 PM
JHA General Scaffold Use	44 KB	Microsoft Word Doc...	9/5/2003 4:26 PM
JHA moving pit shield blocks	43 KB	Microsoft Word Doc...	9/5/2003 4:08 PM
JHA ah1 heater replacement	43 KB	Microsoft Word Doc...	8/15/2003 11:04 AM
JHA closing A pixel layer	40 KB	Microsoft Word Doc...	8/7/2003 11:46 AM
JHA opening A pixel layer	39 KB	Microsoft Word Doc...	8/7/2003 11:33 AM
JHA for UPS battery change	41 KB	Microsoft Word Doc...	11/18/2002 4:06 PM
UVUPUMP_JHA	46 KB	Microsoft Word Doc...	11/8/2002 4:07 PM
JHA South sidewalk scaffolding	31 KB	Microsoft Word Doc...	6/13/2002 8:34 AM